



8131 East 46 Street Tulsa, Oklahoma 74145
 Tel: +1-918-627-8484 Fax: +1-918-627-8446
 Air Agency Certificate No. HJ2R874K

CAPABILITIES LIST
 07-AUG-2025
 REV. D

Part Number	Nomenclature	Engine/Effectivity	ETI INC. DER	Description/Title
691848	BEARING-ASSY OF, COMPR STATOR	JT9D Series	ETI-7038-JT9D	Replace Fabric Liner of Outer Vane Trunnion Bearing(s) in HPC Rear Compressor Inlet (variable) Stator and Rear Compressor Bearing Case Assembly.
691849	BEARING-ASSY OF, COMPR STATOR	JT9D Series	ETI-7038-JT9D	Replace Fabric Liner of Outer Vane Trunnion Bearing(s) in HPC Rear Compressor Inlet (variable) Stator and Rear Compressor Bearing Case Assembly.
A691848	BEARING-ASSY OF, COMPR STATOR	JT9D Series	ETI-7038-JT9D	Replace Fabric Liner of Outer Vane Trunnion Bearing(s) in HPC Rear Compressor Inlet (variable) Stator and Rear Compressor Bearing Case Assembly.
A691849	BEARING-ASSY OF, COMPR STATOR	JT9D Series	ETI-7038-JT9D	Replace Fabric Liner of Outer Vane Trunnion Bearing(s) in HPC Rear Compressor Inlet (variable) Stator and Rear Compressor Bearing Case Assembly.
1A7724	BEARING-HPC	PW2000 Series	ETI-7038-2000	Replace Fabric Liner of Outer Vane Trunnion Bearing(s) in HPC Rear Compressor Inlet (variable) Stator and Rear Compressor Bearing Case Assembly. (ATA Chapter 72-35-61)
1B4168	BEARING-HPC	PW2000 Series	ETI-7038-2000	Replace Fabric Liner of Outer Vane Trunnion Bearing(s) in HPC Rear Compressor Inlet (variable) Stator and Rear Compressor Bearing Case Assembly. (ATA Chapter 72-35-61)
A1B4168	BEARING-HPC	PW2000 Series	ETI-7038-2000	Replace Fabric Liner of Outer Vane Trunnion Bearing(s) in HPC Rear Compressor Inlet (variable) Stator and Rear Compressor Bearing Case Assembly. (ATA Chapter 72-35-61)
1A7724	BEARING-HPC	PW2000 Series All Models	ETI-7038-2000-PL	Plating Repair of worn OD surfaces of HPC Case Trunnion bearings (Inlet and Stage 6, Stage 7, Stage 8, and Stage 9). ATA section 72-35-61 HPC Front Case Assembly Trunnion.
1B4168	BEARING-HPC	PW2000 Series All Models	ETI-7038-2000-PL	Plating Repair of worn OD surfaces of HPC Case Trunnion bearings (Inlet and Stage 6, Stage 7, Stage 8, and Stage 9). ATA section 72-35-61 HPC Front Case Assembly Trunnion.
1A7724	BEARING-HPC	PW2000 Series All Models	ETI-7038-2000-PL	Plating Repair of worn OD surfaces of HPC Case Trunnion bearings (Inlet and Stage 6, Stage 7, Stage 8, and Stage 9). ATA section 72-35-61 HPC Front Case Assembly Trunnion.
1B4168	BEARING-HPC	PW2000 Series All Models	ETI-7038-2000-PL	Plating Repair of worn OD surfaces of HPC Case Trunnion bearings (Inlet and Stage 6, Stage 7, Stage 8, and Stage 9). ATA section 72-35-61 HPC Front Case Assembly Trunnion.
A1B4169	BEARING-HPC	PW2000 Series All Models	ETI-7038-2000-PL	Plating Repair of worn OD surfaces of HPC Case Trunnion bearings (Inlet and Stage 6, Stage 7, Stage 8, and Stage 9). ATA section 72-35-61 HPC Front Case Assembly Trunnion.
50H084	Bearing, HPC Variable Vane	PW4000 Series 94", 100", 112"	ETI-7038-4000	Replace Fabric Liner of Outer Vane Trunnion Bearing(s) in HPC Rear Compressor Inlet (variable) Stator and Rear Compressor Bearing Case Assembly.



8131 East 46 Street Tulsa, Oklahoma 74145
 Tel: +1-918-627-8484 Fax: +1-918-627-8446
 Air Agency Certificate No. HJ2R874K

CAPABILITIES LIST
 07-AUG-2025
 REV. D

Part Number	Nomenclature	Engine/Effectivity	ETI INC. DER	Description/Title
50H499	Bearing, HPC Variable Vane	PW4000 Series 94", 100", 112"	ETI-7038-4000	Replace Fabric Liner of Outer Vane Trunnion Bearing(s) in HPC Rear Compressor Inlet (variable) Stator and Rear Compressor Bearing Case Assembly.
50H500	Bearing, HPC Variable Vane	PW4000 Series 94", 100", 112"	ETI-7038-4000	Replace Fabric Liner of Outer Vane Trunnion Bearing(s) in HPC Rear Compressor Inlet (variable) Stator and Rear Compressor Bearing Case Assembly.
A50H084	Bearing, HPC Variable Vane	PW4000 Series 94", 100", 112"	ETI-7038-4000	Replace Fabric Liner of Outer Vane Trunnion Bearing(s) in HPC Rear Compressor Inlet (variable) Stator and Rear Compressor Bearing Case Assembly.
A50H499	Bearing, HPC Variable Vane	PW4000 Series 94", 100", 112"	ETI-7038-4000	Replace Fabric Liner of Outer Vane Trunnion Bearing(s) in HPC Rear Compressor Inlet (variable) Stator and Rear Compressor Bearing Case Assembly.
A50H500	Bearing, HPC Variable Vane	PW4000 Series 94", 100", 112"	ETI-7038-4000	Replace Fabric Liner of Outer Vane Trunnion Bearing(s) in HPC Rear Compressor Inlet (variable) Stator and Rear Compressor Bearing Case Assembly.
50H084	Bearing, HPC Variable Vane	PW4000 Series 94", 100", 112"	ETI-7038-4000-PL	Plating Repair of worn OD surfaces of HPC Case Trunnion bearings (IGV and Stage 5, Stage 6 and Stage 7). ATA section 72-35-40 HPC Front Case/Outer Airseal.
50H499	Bearing, HPC Variable Vane	PW4000 Series 94", 100", 112"	ETI-7038-4000-PL	Plating Repair of worn OD surfaces of HPC Case Trunnion bearings (IGV and Stage 5, Stage 6 and Stage 7). ATA section 72-35-40 HPC Front Case/Outer Airseal.
50H500	Bearing, HPC Variable Vane	PW4000 Series 94", 100", 112"	ETI-7038-4000-PL	Plating Repair of worn OD surfaces of HPC Case Trunnion bearings (IGV and Stage 5, Stage 6 and Stage 7). ATA section 72-35-40 HPC Front Case/Outer Airseal.
A50H084	Bearing, HPC Variable Vane	PW4000 Series 94", 100", 112"	ETI-7038-4000-PL	Plating Repair of worn OD surfaces of HPC Case Trunnion bearings (IGV and Stage 5, Stage 6 and Stage 7). ATA section 72-35-40 HPC Front Case/Outer Airseal.
A50H499	Bearing, HPC Variable Vane	PW4000 Series 94", 100", 112"	ETI-7038-4000-PL	Plating Repair of worn OD surfaces of HPC Case Trunnion bearings (IGV and Stage 5, Stage 6 and Stage 7). ATA section 72-35-40 HPC Front Case/Outer Airseal.
A50H500	Bearing, HPC Variable Vane	PW4000 Series 94", 100", 112"	ETI-7038-4000-PL	Plating Repair of worn OD surfaces of HPC Case Trunnion bearings (IGV and Stage 5, Stage 6 and Stage 7). ATA section 72-35-40 HPC Front Case/Outer Airseal.
50H765	ARM-ASSY OF, HPC, INLET AND SSTG	PW4000 Series 94", 100"	ETI-7039-4000	Vane Arm Repair of HPC Synchronizing Ring Assemblies



8131 East 46 Street Tulsa, Oklahoma 74145
 Tel: +1-918-627-8484 Fax: +1-918-627-8446
 Air Agency Certificate No. HJ2R874K

CAPABILITIES LIST
 07-AUG-2025
 REV. D

Part Number	Nomenclature	Engine/Effectivity	ETI INC. DER	Description/Title
51H147-01	ARM-ASSY OF, HPC, 6 AND 7STG PRE * SB PW4ENG 72-837	PW4000 Series 94", 100"	ETI-7039-4000	Vane Arm Repair of HPC Synchronizing Ring Assemblies
JA50H765	ARM-ASSY OF, HPC, INLET AND 5STG	PW4000 Series 94", 100"	ETI-7039-4000	Vane Arm Repair of HPC Synchronizing Ring Assemblies
JA51H147-01	ARM-ASSY OF, HPC, 6 AND 7STG PRE * SB PW4ENG 72-837	PW4000 Series 94", 100"	ETI-7039-4000	Vane Arm Repair of HPC Synchronizing Ring Assemblies
55H838-01	ARM-ASSY OF, HPC, INLET AND 5STG PRE * SB PW4G-112-72-134 REF * SB PW4G-112-72-137	PW4000 Series 100", 112"	ETI-7039-4001	Vane Arm Repair of HPC Synchronizing Ring Assemblies
55H839-01	ARM-ASSY OF, HPC, 6 AND 7STG PRE SB PW4G-112-72-135	PW4000 Series 100", 112"	ETI-7039-4001	Vane Arm Repair of HPC Synchronizing Ring Assemblies
JA55H838-01	ARM-ASSY OF, HPC, INLET AND 5STG PRE * SB PW4G-112-72-134 REF * SB PW4G-112-72-137	PW4000 Series 100", 112"	ETI-7039-4001	Vane Arm Repair of HPC Synchronizing Ring Assemblies
JA55H839-01	ARM-ASSY OF, HPC, 6 AND 7STG PRE SB PW4G-112-72-135	PW4000 Series 100", 112"	ETI-7039-4001	Vane Arm Repair of HPC Synchronizing Ring Assemblies
JA55H923-01	ARM-ASSY OF, HPC, 6 AND 7STG POST * SB PW4ENG 72-837	PW4000 Series 100", 112"	ETI-7039-4002	Vane Arm Repair of HPC Synchronizing Ring Assemblies
JA55H922-01	ARM-ASSY OF, HPC, INLET AND 5STG POST * SB PW4G-112-72-134	PW4000 Series 100", 112"	ETI-7039-4002	Vane Arm Repair of HPC Synchronizing Ring Assemblies
55H922-01	ARM-ASSY OF, HPC, INLET AND 5STG POST * SB PW4G-112-72-134	PW4000 Series 100", 112"	ETI-7039-4002	Vane Arm Repair of HPC Synchronizing Ring Assemblies
55H923-01	ARM-ASSY OF, HPC, 6 AND 7STG POST * SB PW4ENG 72-837	PW4000 Series 100", 112"	ETI-7039-4002	Vane Arm Repair of HPC Synchronizing Ring Assemblies



8131 East 46 Street Tulsa, Oklahoma 74145

Tel: +1-918-627-8484 Fax: +1-918-627-8446

Air Agency Certificate No. HJ2R874K

CAPABILITIES LIST

07-AUG-2025

REV. D

Part Number	Nomenclature	Engine/Effectivity	ETI INC. DER	Description/Title
56H103-001	TUBE- REIDENT FROM ASSY OF, HPC DISK, 9STG POST * SB PW4ENG 72-814	PW4052, PW4052(-3), PW4056, PW4056(-3), PW4060, PW4060(-3), PW4060A, PW4062(-3), PW4062A(-3), PW4152, PW4152(-3), PW4156A, PW4156A(-3), PW4158, PW4158(-3), PW4460, PW4460(-3), PW4462, PW4462(-3)	ETI-7044	Salvage Repair of 9th Stage HPC Bleed Anti-Vortex tube Assembly
50H045	TUBE-ASSY OF, HPC DISK, 9STG PRE * SB PW4ENG 72-641	PW4052, PW4052(-3), PW4056, PW4056(-3), PW4060, PW4060(-3), PW4060A, PW4062(-3), PW4062A(-3), PW4152, PW4152(-3), PW4156A, PW4156A(-3), PW4158, PW4158(-3), PW4460, PW4460(-3), PW4462, PW4462(-3)	ETI-7044	Salvage Repair of 9th Stage HPC Bleed Anti-Vortex tube Assembly
56H103	TUBE-ASSY OF, HPC DISK, 9STG POST * SB PW4ENG 72-641 PRE SB PW4ENG 72-758 PRE * SB PW4ENG 72-814	PW4052, PW4052(-3), PW4056, PW4056(-3), PW4060, PW4060(-3), PW4060A, PW4062(-3), PW4062A(-3), PW4152, PW4152(-3), PW4156A, PW4156A(-3), PW4158, PW4158(-3), PW4460, PW4460(-3), PW4462, PW4462(-3)	ETI-7044	Salvage Repair of 9th Stage HPC Bleed Anti-Vortex tube Assembly
50S222	TUBE-ASSY OF, HPC DISK, 9STG POST * SB PW4ENG 72-814	PW4052, PW4052(-3), PW4056, PW4056(-3), PW4060, PW4060(-3), PW4060A, PW4062(-3), PW4062A(-3), PW4152, PW4152(-3), PW4156A, PW4156A(-3), PW4158, PW4158(-3), PW4460, PW4460(-3), PW4462, PW4462(-3)	ETI-7044	Salvage Repair of 9th Stage HPC Bleed Anti-Vortex tube Assembly
1B3439-01	TUBE-ASSY OF, HPC, DISK 13STG POST SB PW2000 72-338 PRE SB PW2000 72-402 PRE SB PW2000 72-539 PRE SB PW2000 72-572	PW2037, PW2037(M), PW2040, PW2240, PW2337	ETI-7044-2000	Salvage Repair of 9th Stage HPC Bleed Anti-Vortex tube Assembly
1B5879-01	TUBE-ASSY OF, HPC, DISK 13STG POST SB PW2000 72-402 PRE SB PW2000 72-539 PRE SB PW2000 72-546 PRE SB PW2000 72-572	PW2037, PW2037(M), PW2040, PW2240, PW2337	ETI-7044-2000	Salvage Repair of 9th Stage HPC Bleed Anti-Vortex tube Assembly



8131 East 46 Street Tulsa, Oklahoma 74145
 Tel: +1-918-627-8484 Fax: +1-918-627-8446
 Air Agency Certificate No. HJ2R874K

CAPABILITIES LIST
 07-AUG-2025
 REV. D

Part Number	Nomenclature	Engine/Effectivity	ETI INC. DER	Description/Title
1B7351-01	TUBE-ASSY OF, HPC DISK, 13STG POST SB PW2000 72-539 POST SB PW2000 72-546 PRE SB PW2000 72-572	PW2037, PW2037(M), PW2040, PW2240, PW2337	ETI-7044-2000	Salvage Repair of 9th Stage HPC Bleed Anti-Vortex tube Assembly
1B7379-01	TUBE-ASSY OF, HPC, DISK 13STG POST SB PW2000 72-572	PW2037, PW2037(M), PW2040, PW2240, PW2337	ETI-7044-2000	Salvage Repair of 9th Stage HPC Bleed Anti-Vortex tube Assembly
56H104-01	TUBE-ASSY OF, BLEED, HPC, 9STG POST * SB PW4ENG 72-641 POST SB PW4ENG 72-647 POST SB PW4ENG 72-758 PRE * SB PW4ENG 72-814	PW4000 Series	ETI-7044-4000	Salvage Repair of 9th Stage HPC Bleed Anti-Vortex tube Assembly
53H330-01	TUBE-ASSY OF, BLEED, HPC, 9STG PRE SB PW4ENG 72-607 PRE * SB PW4ENG 72-641 POST SB PW4ENG 72-647	PW4000 Series	ETI-7044-4000	Salvage Repair of 9th Stage HPC Bleed Anti-Vortex tube Assembly
55H667-01	TUBE-ASSY OF, BLEED, HPC, 9STG USE AS A COMPLETE SET POST SB PW4ENG 72-607 PRE * SB PW4ENG 72-641 POST SB PW4ENG 72-647	PW4000 Series	ETI-7044-4000	Salvage Repair of 9th Stage HPC Bleed Anti-Vortex tube Assembly
56H101-01	TUBE-ASSY OF, BLEED, HPC, 9STG POST SB PW4G-112-72-183	PW4084D, PW4077D, PW4074D, PW4090	ETI-7044-4001	Salvage Repair of 9th Stage HPC Bleed Anti-Vortex tube Assembly
56H102-01	TUBE-ASSY OF, BLEED, HPC, 9STG POST SB PW4G-112-72-183	PW4084D, PW4077D, PW4074D, PW4090	ETI-7044-4001	Salvage Repair of 9th Stage HPC Bleed Anti-Vortex tube Assembly
55H852-01	TUBE-ASSY OF, BLEED, HPC, 9STG PRE SB PW4G-112-72-183	PW4084D, PW4077D, PW4074D, PW4090	ETI-7044-4001	Salvage Repair of 9th Stage HPC Bleed Anti-Vortex tube Assembly
55H997-01	TUBE-ASSY OF, BLEED, HPC, 9STG PRE SB PW4G-112-72-183	PW4084D, PW4077D, PW4074D, PW4090	ETI-7044-4001	Salvage Repair of 9th Stage HPC Bleed Anti-Vortex tube Assembly
9295M30G05	RING-STG 3 SEG ASSY ACTN	CF6 Engine Series	ETI-7045	Salvage Repair of IGV - 4th Stage Vane Actuation Ring Segment
6A6514	PAD - A/O,CENTRALIZING-ST.3 POST SBE72-0277	V2500	ETI-7066	Replacement of Wear resistant Composite cloth of Stage 3-6 Centralizing Pad
6A3957	PAD - A/O,CENTRALIZING-ST.3 POST SBE72-0027 PRE SBE72-0277	V2500	ETI-7066	Replacement of Wear resistant Composite cloth of Stage 3-6 Centralizing Pad
6A2467	PAD - A/O,CENTRALIZING-ST.3 PRE SBE72-0027	V2500	ETI-7066	Replacement of Wear resistant Composite cloth of Stage 3-6 Centralizing Pad
6A2468	PAD - A/O,CENTRALIZING-ST.4 PRE SBE72-0027	V2500	ETI-7066	Replacement of Wear resistant Composite cloth of Stage 3-6 Centralizing Pad



8131 East 46 Street Tulsa, Oklahoma 74145
 Tel: +1-918-627-8484 Fax: +1-918-627-8446
 Air Agency Certificate No. HJ2R874K

CAPABILITIES LIST
 07-AUG-2025
 REV. D

Part Number	Nomenclature	Engine/Effectivity	ETI INC. DER	Description/Title
6A3958	PAD - A/O,CENTRALIZING-ST.4 POST SBE72-0591	V2500	ETI-7066	Replacement of Wear resistant Composite cloth of Stage 3-6 Centralizing Pad
6A7394	PAD, A/O, CENTRALIZING-ST.4 ALT 6A2468 POST SBE72-0319	V2500	ETI-7066	Replacement of Wear resistant Composite cloth of Stage 3-6 Centralizing Pad
6A3091	PAD -ST. 5 PRE SBE72-0319	V2500	ETI-7066	Replacement of Wear resistant Composite cloth of Stage 3-6 Centralizing Pad
6A7395	PAD - ST.5 ALT 6A3091 POST SBE72-0319	V2500	ETI-7066	Replacement of Wear resistant Composite cloth of Stage 3-6 Centralizing Pad
6A2470	PAD - A/O,CENTRALIZING-ST.6 PRE SBE72-0027	V2500	ETI-7066	Replacement of Wear resistant Composite cloth of Stage 3-6 Centralizing Pad
6A3959	PAD - A/O,CENTRALIZING-ST.6 POST SBE72-0027 POST SBE72-0591	V2500	ETI-7066	Replacement of Wear resistant Composite cloth of Stage 3-6 Centralizing Pad
50N444	DUCT-ASSY OF, LPT, 3STG POST SB PW4ENG 72-342	PW4050, PW4052, PW4056, PW4060, PW4060A, PW4152, PW4156, PW4158, PW5560	ETI-7077	PW4000 Stage 3 LPT Duct - New Shell
50N445-01	DUCT SEGMENT-ASSY OF, LPT, 3STG POST SB PW4ENG 72-342	PW4050, PW4052, PW4056, PW4060, PW4060A, PW4152, PW4156, PW4158, PW5560	ETI-7077	PW4000 Stage 3 LPT Duct - New Shell
50N446-01	DUCT SEGMENT-ASSY OF, LPT, 3STG POST SB PW4ENG 72-342	PW4050, PW4052, PW4056, PW4060, PW4060A, PW4152, PW4156, PW4158, PW5560	ETI-7077	PW4000 Stage 3 LPT Duct - New Shell
50N307-01	DUCT SEGMENT-ASSY OF, LPT, 3STG POST * SB PW4ENG 72-209 PRE SB PW4ENG 72-342	PW4050, PW4052, PW4056, PW4060, PW4060A, PW4152, PW4156, PW4158, PW5560	ETI-7077	PW4000 Stage 3 LPT Duct - New Shell
50N308-01	DUCT SEGMENT-ASSY OF, LPT, 3STG POST * SB PW4ENG 72-209 PRE SB PW4ENG 72-342	PW4050, PW4052, PW4056, PW4060, PW4060A, PW4152, PW4156, PW4158, PW5560	ETI-7077	PW4000 Stage 3 LPT Duct - New Shell
3535-196	RETAINER, DRIVE PIN	CFM56-5A, -5B, and -5C	ETI-7081	Salvage Repair of the Drive Pin Retainer Assembly
50N241	SHIELD OPTION PRE SB PW4ENG 72-593 PROCURE NO C/O 50N119-01 AND 50N120-01	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
50N119-01	..SHIELD-ASSY OF, HEAT, TURB CASE	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
50N120-01	..SHIELD-ASSY OF, HEAT, TURB CASE	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case



8131 East 46 Street Tulsa, Oklahoma 74145
 Tel: +1-918-627-8484 Fax: +1-918-627-8446
 Air Agency Certificate No. HJ2R874K

CAPABILITIES LIST
 07-AUG-2025
 REV. D

Part Number	Nomenclature	Engine/Effectivity	ETI INC. DER	Description/Title
50N242	.SHIELD OPTION PROCURE NO C/O 50N121-01 AND 50N122-01	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
50N121-01	..SHIELD-ASSY OF, HEAT, TURB CASE	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
50N122-01	..SHIELD-ASSY OF, HEAT, TURB CASE	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
50N542	SHIELD OPTION PROCURE NO C/O 50N546-01 AND 50N548-01 POST SB PW4ENG 72-593	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
50N546-01	..SHIELD-ASSY OF, HEAT, TURB CASE	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
50N548-01	..SHIELD-ASSY OF, HEAT, TURB CASE	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
50N243	SHIELD OPTION PROCURE NO C/O 50N123-01 AND 50N124-01 PRE SB PW4ENG 72-593	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
50N123-01	..SHIELD-ASSY OF, HEAT, TURB CASE	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
50N124-01	..SHIELD-ASSY OF, HEAT, TURB CASE	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
50N541	SHIELD OPTION PROCURE NO C/O 50N547-01 AND 50N549-01 POST SB PW4ENG 72-593	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
50N547-01	..SHIELD-ASSY OF, HEAT, TURB CASE	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case



8131 East 46 Street Tulsa, Oklahoma 74145
 Tel: +1-918-627-8484 Fax: +1-918-627-8446
 Air Agency Certificate No. HJ2R874K

CAPABILITIES LIST
 07-AUG-2025
 REV. D

Part Number	Nomenclature	Engine/Effectivity	ETI INC. DER	Description/Title
50N549-01	..SHIELD-ASSY OF, HEAT, TURB CASE	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
50N244	SHIELD OPTION PROCURE NO C/O 50N125-01 AND 50N126-01	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
50N125-01	..SHIELD-ASSY OF, HEAT, TURB CASE	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
50N126-01	..SHIELD-ASSY OF, HEAT, TURB CASE	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
50N245	SHIELD OPTION PROCURE NO C/O 50N127-01 AND 50N128-01	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
50N127-01	..SHIELD-ASSY OF, HEAT, TURB CASE	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
50N128-01	..SHIELD-ASSY OF, HEAT, TURB CASE	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
50N246	SHIELD OPTION PROCURE NO C/O 50N129-01 AND 50N130-01	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
50N129-01	..SHIELD-ASSY OF, HEAT, TURB CASE	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
50N130-01	..SHIELD-ASSY OF, HEAT, TURB CASE	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
50N421-01	SHIELD-ASSY OF, HEAT, TURB CASE	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
50N423-01	SHIELD-ASSY OF, HEAT, TURB CASE	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
50N564-01	SHIELD-ASSY OF, HEAT, TURB CASE PRE SB PW4G-100-72-135	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
50N322-01	SHIELD-ASSY OF, HEAT, TURB CASE POST SB PW4G-100-72-135	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
50N565-01	SHIELD-ASSY OF, HEAT, TURB CASE PRE SB PW4G-100-72-135	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case



8131 East 46 Street Tulsa, Oklahoma 74145
 Tel: +1-918-627-8484 Fax: +1-918-627-8446
 Air Agency Certificate No. HJ2R874K

CAPABILITIES LIST
 07-AUG-2025
 REV. D

Part Number	Nomenclature	Engine/Effectivity	ETI INC. DER	Description/Title
52M097	INSULATION SEGMENT-THERMAL, 3STG POST * SB PW4G-112-72-28	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
52M098	INSULATION SEGMENT-4STG POST * SB PW4G-112-72-28	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
52M099	INSULATION SEGMENT-THERMAL, 4STG POST * SB PW4G-112-72-28	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
52M101	INSULATION SEGMENT-5STG POST * SB PW4G-112-72-28	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
52M102	INSULATION SEGMENT-THERMAL, 5STG POST * SB PW4G-112-72-28	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
52M103	INSULATION SEGMENT-6STG POST * SB PW4G-112-72-28	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
52M104	INSULATION SEGMENT-THERMAL, 6STG POST * SB PW4G-112-72-28	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
52M105	INSULATION SEGMENT-7STG POST * SB PW4G-112-72-28	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
52M106	INSULATION-THERMAL, 7STG POST * SB PW4G-112-72-28 PRE SB PW4G-112-72-227	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
52M107	INSULATION SEGMENT-8STG POST * SB PW4G-112-72-28	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
52M108	SEAL SEGMENT-8STG POST * SB PW4G-112-72-28	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
53M770	INSULATION-THERMAL, 7STG POST SB PW4G-112-72-227	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
53M286	INSULATION SEGMENT-7STG	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
53M287	INSULATION SEGMENT-7STG	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
53M288	INSULATION SEGMENT-7STG	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
53M289	INSULATION SEGMENT-7STG	PW4000, 94"/100"/112"	ETI-7091	Salvage repair of thermal heat shield of LPT Case
5008476	SCREEN, INSEPARABLE ASSY	Hamilton Sundstrand / International Aero Engines V2500 Series, All Models	ETI-7093	Salvage repair of the Fuel Gear Pump Screen
5009913	SCREEN, INSEPARABLE ASSY	Hamilton Sundstrand / International Aero Engines V2500 Series, All Models	ETI-7093	Salvage repair of the Fuel Gear Pump Screen
4001-25	Valve, Check	CF34-8C	ETI-7099	Salvage repair of the 6th Stage Check Valve
50M459	SHIELD-ASSY OF, HEAT, 6STG	PW4000 112" Models	ETI-7118	Salvage repair of LPT Heat Shield assembly



8131 East 46 Street Tulsa, Oklahoma 74145
 Tel: +1-918-627-8484 Fax: +1-918-627-8446
 Air Agency Certificate No. HJ2R874K

CAPABILITIES LIST
 07-AUG-2025
 REV. D

Part Number	Nomenclature	Engine/Effectivity	ETI INC. DER	Description/Title
53M471	SHIELD-ASSY OF, HEAT, 4STG	PW4000 112" Models	ETI-7118	Salvage repair of LPT Heat Shield assembly
53M640	SHIELD-ASSY OF, HEAT, 5STG POST SB PW4G-112-72-179	PW4000 112" Models	ETI-7118	Salvage repair of LPT Heat Shield assembly
53M641	SHIELD-ASSY OF, HEAT, 5STG POST SB PW4G-112-72-179	PW4000 112" Models	ETI-7118	Salvage repair of LPT Heat Shield assembly
51M441	SHIELD-ASSY OF, HEAT, 8STG	PW4000 112" Models	ETI-7118	Salvage repair of LPT Heat Shield assembly
52M306	SHIELD-ASSY OF, HEAT, 7STG POST SB PW4G-112-72-24	PW4000 112" Models	ETI-7118	Salvage repair of LPT Heat Shield assembly
58H418	SHIELD-HEAT, COMPR, UPPER INNER REAR, 12STG POST * SB PW4ENG 72-755	PW4052, PW4056, PW4060, PW4060C, PW4062, PW4152, PW4156A, PW4158, PW4164, PW4168, PW4168A, PW4170, PW4460, PW4462	ETI-7122	Salvage repair of the 12th & 13th stage HPC HEAT SHIELD
58H419	SHIELD-HEAT, COMPR, LOWER INNER REAR, 12STG POST * SB PW4ENG 72-755	PW4052, PW4056, PW4060, PW4060C, PW4062, PW4152, PW4156A, PW4158, PW4164, PW4168, PW4168A, PW4170, PW4460, PW4462	ETI-7122	Salvage repair of the 12th & 13th stage HPC HEAT SHIELD
58H420	SHIELD-HEAT, COMPR, LEFT OUTER REAR, 12STG POST * SB PW4ENG 72-755	PW4052, PW4056, PW4060, PW4060C, PW4062, PW4152, PW4156A, PW4158, PW4164, PW4168, PW4168A, PW4170, PW4460, PW4462	ETI-7122	Salvage repair of the 12th & 13th stage HPC HEAT SHIELD
58H424	SHIELD-HEAT, COMPR, RIGHT OUTER REAR, 12STG POST * SB PW4ENG 72-755	PW4052, PW4056, PW4060, PW4060C, PW4062, PW4152, PW4156A, PW4158, PW4164, PW4168, PW4168A, PW4170, PW4460, PW4462	ETI-7122	Salvage repair of the 12th & 13th stage HPC HEAT SHIELD
50S027	SHIELD-HEAT, COMPR, 13STG POST * SB PW4ENG 72-755	PW4052, PW4056, PW4060, PW4060C, PW4062, PW4152, PW4156A, PW4158, PW4164, PW4168, PW4168A, PW4170, PW4460, PW4462	ETI-7122	Salvage repair of the 12th & 13th stage HPC HEAT SHIELD
50R280-01	Oil Tank Heat Shield	PW4000 Series	ETI-7124	Salvage repair of the Oil Tank Thermal Heat Shield assembly
51R059-01	Oil Tank Heat Shield Post SB PW4ENG 79-65	PW4000 Series	ETI-7124	Salvage repair of the Oil Tank Thermal Heat Shield assembly
96319	PIVOT PAD ASSY	Goodrich Cargo Systems	ETI-7127	Salvage repair of the Pivot Pad assembly
96319A	PIVOT PAD ASSY	Goodrich Cargo Systems	ETI-7127	Salvage repair of the Pivot Pad assembly
793178-01	SHIELD-ASSY OF, HEAT, TURB CASE PRE * SB JT9D-7R4-72-484	JT9D-7R4 Series	ETI-7130	Salvage repair of the 3rd, 4th, and 5th Stage Turbine Case Heat Shields.
802798-01	SHIELD-ASSY OF, HEAT, TURB CASE POST * SB JT9D-7R4-72-325	JT9D-7R4 Series	ETI-7130	Salvage repair of the 3rd, 4th, and 5th Stage Turbine Case Heat Shields.
793180-01	SHIELD-ASSY OF, HEAT, TURB CASE PRE * SB JT9D-7R4-72-325	JT9D-7R4 Series	ETI-7130	Salvage repair of the 3rd, 4th, and 5th Stage Turbine Case Heat Shields.



8131 East 46 Street Tulsa, Oklahoma 74145
 Tel: +1-918-627-8484 Fax: +1-918-627-8446
 Air Agency Certificate No. HJ2R874K

CAPABILITIES LIST
 07-AUG-2025
 REV. D

Part Number	Nomenclature	Engine/Effectivity	ETI INC. DER	Description/Title
802799-01	SHIELD-ASSY OF, HEAT, TURB CASE POST * SB JT9D-7R4-72-325	JT9D-7R4 Series	ETI-7130	Salvage repair of the 3rd, 4th, and 5th Stage Turbine Case Heat Shields.
793234-01	SHIELD-ASSY OF, HEAT, TURB CASE PRE * SB JT9D-7R4-72-325	JT9D-7R4 Series	ETI-7130	Salvage repair of the 3rd, 4th, and 5th Stage Turbine Case Heat Shields.
808133-01	SHIELD-ASSY OF, HEAT, TURB CASE POST SB JT9D-7R4-72-420	JT9D-7R4 Series	ETI-7130	Salvage repair of the 3rd, 4th, and 5th Stage Turbine Case Heat Shields.
802797-01	SHIELD-ASSY OF, HEAT, TURB CASE POST * SB JT9D-7R4-72-325 PRE SB JT9D-7R4-72-420	JT9D-7R4 Series	ETI-7130	Salvage repair of the 3rd, 4th, and 5th Stage Turbine Case Heat Shields.
813075-01	SHIELD-ASSY OF, HEAT, TURB CASE POST * SB JT9D-7R4-72-484	JT9D-7R4 Series	ETI-7130	Salvage repair of the 3rd, 4th, and 5th Stage Turbine Case Heat Shields.
793182-01	SHIELD-ASSY OF, HEAT, TURB CASE PRE * SB JT9D-7R4-72-484	JT9D-7R4 Series	ETI-7130	Salvage repair of the 3rd, 4th, and 5th Stage Turbine Case Heat Shields.
813076-01	SHIELD-ASSY OF, HEAT, TURB CASE POST * SB JT9D-7R4-72-484	JT9D-7R4 Series	ETI-7130	Salvage repair of the 3rd, 4th, and 5th Stage Turbine Case Heat Shields.
793235-01	SHIELD-ASSY OF, HEAT, TURB CASE PRE * SB JT9D-7R4-72-484	JT9D-7R4 Series	ETI-7130	Salvage repair of the 3rd, 4th, and 5th Stage Turbine Case Heat Shields.
793179-01	SHIELD-ASSY OF, HEAT, TURB CASE PRE * SB JT9D-7R4-72-484	JT9D-7R4 Series	ETI-7130	Salvage repair of the 3rd, 4th, and 5th Stage Turbine Case Heat Shields.
813077-01	SHIELD-ASSY OF, HEAT, TURB CASE POST * SB JT9D-7R4-72-484	JT9D-7R4 Series	ETI-7130	Salvage repair of the 3rd, 4th, and 5th Stage Turbine Case Heat Shields.
793184-01	SHIELD-ASSY OF, HEAT, TURB CASE PRE * SB JT9D-7R4-72-484	JT9D-7R4 Series	ETI-7130	Salvage repair of the 3rd, 4th, and 5th Stage Turbine Case Heat Shields.
6B1285	LEVER - VSV5 BALL DOWN, ASSEMBLY OF, POST SBE72-0571	V2500-A5 Engine models	ETI-7150	LEVER BALL AND PIN REPAIR OF HPC VSV LEVER ARM ASSEMBLIES
6B1294	LEVER - VSV5 BALL DOWN, ASSEMBLY OF, POST SBE72-0571	V2500-A5 Engine models	ETI-7150	LEVER BALL AND PIN REPAIR OF HPC VSV LEVER ARM ASSEMBLIES
6B1286	LEVER - VSV5 BALL UP, ASSEMBLY OF, POST SBE72-0571	V2500-A5 Engine models	ETI-7150	LEVER BALL AND PIN REPAIR OF HPC VSV LEVER ARM ASSEMBLIES
6B1295	LEVER - VSV5 BALL UP, ASSEMBLY OF, POST SBE72-0571	V2500-A5 Engine models	ETI-7150	LEVER BALL AND PIN REPAIR OF HPC VSV LEVER ARM ASSEMBLIES
6B1282	LEVER - VSV4 STANDARD, ASSEMBLY OF, POST SBE72-0571	V2500-A5 Engine models	ETI-7150	LEVER BALL AND PIN REPAIR OF HPC VSV LEVER ARM ASSEMBLIES
6B1291	LEVER - VSV4 STANDARD, ASSEMBLY OF, POST SBE72-0571	V2500-A5 Engine models	ETI-7150	LEVER BALL AND PIN REPAIR OF HPC VSV LEVER ARM ASSEMBLIES
6B1283	LEVER - VSV4 TDC, ASSEMBLY OF, POST SBE72-0571	V2500-A5 Engine models	ETI-7150	LEVER BALL AND PIN REPAIR OF HPC VSV LEVER ARM ASSEMBLIES
6B1292	LEVER - VSV4 TDC, ASSEMBLY OF, POST SBE72-0571	V2500-A5 Engine models	ETI-7150	LEVER BALL AND PIN REPAIR OF HPC VSV LEVER ARM ASSEMBLIES



8131 East 46 Street Tulsa, Oklahoma 74145

Tel: +1-918-627-8484 Fax: +1-918-627-8446

Air Agency Certificate No. HJ2R874K

CAPABILITIES LIST

07-AUG-2025

REV. D

Part Number	Nomenclature	Engine/Effectivity	ETI INC. DER	Description/Title
6B1284	LEVER - VSV4 CRANKED UP, ASSEMBLY OF, POST SBE72-0571	V2500-A5 Engine models	ETI-7150	LEVER BALL AND PIN REPAIR OF HPC VSV LEVER ARM ASSEMBLIES
6B1293	LEVER - VSV4 CRANKED UP, ASSEMBLY OF, POST SBE72-0571	V2500-A5 Engine models	ETI-7150	LEVER BALL AND PIN REPAIR OF HPC VSV LEVER ARM ASSEMBLIES
6B1279	LEVER - VSV3 STANDARD, ASSEMBLY OF, POST SBE72-0571	V2500-A5 Engine models	ETI-7150	LEVER BALL AND PIN REPAIR OF HPC VSV LEVER ARM ASSEMBLIES
6B1288	LEVER - VSV3 STANDARD, ASSEMBLY OF, POST SBE72-0571	V2500-A5 Engine models	ETI-7150	LEVER BALL AND PIN REPAIR OF HPC VSV LEVER ARM ASSEMBLIES
6B1280	LEVER - VSV3 BALL UP, ASSEMBLY OF, POST SBE72-0571	V2500-A5 Engine models	ETI-7150	LEVER BALL AND PIN REPAIR OF HPC VSV LEVER ARM ASSEMBLIES
6B1289	LEVER - VSV3 BALL UP, ASSEMBLY OF, POST SBE72-0571	V2500-A5 Engine models	ETI-7150	LEVER BALL AND PIN REPAIR OF HPC VSV LEVER ARM ASSEMBLIES
6B1281	LEVER - VSV3 CRANKED, ASSEMBLY OF, POST SBE72-0571	V2500-A5 Engine models	ETI-7150	LEVER BALL AND PIN REPAIR OF HPC VSV LEVER ARM ASSEMBLIES
6B1290	LEVER - VSV3 CRANKED, ASSEMBLY OF, POST SBE72-0571	V2500-A5 Engine models	ETI-7150	LEVER BALL AND PIN REPAIR OF HPC VSV LEVER ARM ASSEMBLIES
6B1308	LEVER - VARIABLE INLET GUIDE VANES BALL UP, ASSEMBLY OF, POST SBE72-0571	V2500-A5 Engine models	ETI-7150	LEVER BALL AND PIN REPAIR OF HPC VSV LEVER ARM ASSEMBLIES
6B1309	LEVER - VARIABLE INLET GUIDE VANES BALL UP, ASSEMBLY OF, POST SBE72-0571	V2500-A5 Engine models	ETI-7150	LEVER BALL AND PIN REPAIR OF HPC VSV LEVER ARM ASSEMBLIES
6B1278	LEVER - VARIABLE INLET GUIDE VANES STANDARD, ASSEMBLY OF, POST SBE72-0571	V2500-A5 Engine models	ETI-7150	LEVER BALL AND PIN REPAIR OF HPC VSV LEVER ARM ASSEMBLIES
6B1287	LEVER - VARIABLE INLET GUIDE VANES STANDARD, ASSEMBLY OF, POST SBE72-0571	V2500-A5 Engine models	ETI-7150	LEVER BALL AND PIN REPAIR OF HPC VSV LEVER ARM ASSEMBLIES
54H799-01	Synchronizing Ring	PW4000 Series	N/A	PW CIR Manual Repairs
54H887	Synchronizing Ring	PW4000 Series	N/A	PW CIR Manual Repairs
54H798-01	Synchronizing Ring	PW4000 Series	N/A	PW CIR Manual Repairs
55H635-01	Synchronizing Ring	PW4000 Series	N/A	PW CIR Manual Repairs
2039741-0501	Tray		N/A	Customer Provided Repair Data
2041213-0413	Tray		N/A	Customer Provided Repair Data
370313	Yoke		N/A	Customer Provided Repair Data